

2



**US Army Corps
of Engineers**

Construction Engineering
Research Laboratory



**US Army Corps
of Engineers**

Cold Regions Research &
Engineering Laboratory

USACERL Technical Manuscript M-90/02
October 1989

AD-A214 032

ROOFER: A Management Tool For Maintaining Built-Up Roofs

by:

David M. Bailey
Donald E. Brotherson
Wayne Tobiasson

This paper describes ROOFER, a roofing maintenance management system for built-up roofs being developed by the U.S. Army Construction Engineering Research Laboratory with the assistance of the U.S. Army Cold Regions Research and Engineering Laboratory and the U.S. Army Engineering and Housing Support Center. ROOFER provides building managers with a practical tool for evaluating built-up roofs, determining maintenance priorities, and selecting repair strategies that ensure the maximum return on investment.

ROOFER comprises procedures for dividing the building roof into manageable sections, collecting and managing inventory information, inspecting and evaluating condition, and managing networks and projects.

This paper is reprinted with permission from the Proceedings of the 9th Conference on Roofing Technology, "Putting Roofing Technology to Work," May 4-5, 1989, Gaithersburg, Maryland.

DTIC
ELECTE
NOV 03 1989
S B D

Approved for public release; distribution is unlimited.

88 11 024

The contents of this report are not to be used for advertising, publication, or promotional purposes. Citation of trade names does not constitute an official indorsement or approval of the use of such commercial products. The findings of this report are not to be construed as an official Department of the Army position, unless so designated by other authorized documents.

DESTROY THIS REPORT WHEN IT IS NO LONGER NEEDED

DO NOT RETURN IT TO THE ORIGINATOR

REPORT DOCUMENTATION PAGE				Form Approved OMB No 0704 0188 Exp Date Jun 30 1986	
1a REPORT SECURITY CLASSIFICATION UNCLASSIFIED			1b RESTRICTIVE MARKINGS		
2a SECURITY CLASSIFICATION AUTHORITY			3 DISTRIBUTION/AVAILABILITY OF REPORT Approved for public release; distribution is unlimited.		
2b DECLASSIFICATION/DOWNGRADING SCHEDULE					
4 PERFORMING ORGANIZATION REPORT NUMBER(S)			5 MONITORING ORGANIZATION REPORT NUMBER(S)		
6a NAME OF PERFORMING ORGANIZATION SEE REVERSE		6b OFFICE SYMBOL (if applicable)	7a NAME OF MONITORING ORGANIZATION		
6c ADDRESS (City, State, and ZIP Code) SEE REVERSE			7b ADDRESS (City, State, and ZIP Code)		
8a NAME OF FUNDING SPONSORING ORGANIZATION HQUSACE		8b OFFICE SYMBOL (if applicable)	9 PROCUREMENT INSTRUMENT IDENTIFICATION NUMBER		
8c ADDRESS (City, State, and ZIP Code) 20 Massachusetts Avenue, NW. Washington, DC 20314-1000			10 SOURCE OF FUNDING NUMBERS		
			PROGRAM ELEMENT NO 4A162731	PROJECT NO AT41	TASK NO C
11 TITLE (Include Security Classification) "ROOFER: A Management Tool For Maintaining Built-Up Roofs" (U)					
12 PERSONAL AUTHOR(S) Bailey, David M., Brotherson, Donald E., Tobiasson, Wayne					
13a TYPE OF REPORT final		13b TIME COVERED FROM _____ TO _____		14 DATE OF REPORT (Year, Month, Day) 1989, October	
15 PAGE COUNT 11					
16 SUPPLEMENTARY NOTATION Copies are available from the National Technical Information Service, 5285 Port Royal Road, Springfield, VA 22161.					
17 COSATI CODES			18 SUBJECT TERMS (Continue on reverse if necessary and identify by block number) ROOFER built-up roofs maintenance		
FIELD	GROUP	SUB-GROUP			
13	13				
19 ABSTRACT (Continue on reverse if necessary and identify by block number) This paper describes ROOFER, a roofing maintenance management system for built-up roofs being developed by the U.S. Army Construction Engineering Research Laboratory with the assistance of the U.S. Army Cold Regions Research and Engineering Laboratory and the U.S. Army Engineering and Housing Support Center. ROOFER provides building managers with a practical tool for evaluating built-up roofs, determining maintenance priorities, and selecting repair strategies that ensure the maximum return on investment. ROOFER comprises procedures for dividing the building roof into manageable sections, collecting and managing inventory information, inspecting and evaluating condition, and managing networks and projects. This paper is reprinted with permission from the Proceedings of the 9th Conference on Roofing Technology, "Putting Roofing Technology to Work," May 4-5, 1989, Gaithersburg, Maryland.					
20 DISTRIBUTION/AVAILABILITY OF ABSTRACT <input type="checkbox"/> UNCLASSIFIED-UNLIMITED <input checked="" type="checkbox"/> SAME AS RPT <input type="checkbox"/> DTIC USERS			21 ABSTRACT SECURITY CLASSIFICATION		
22a NAME OF RESPONSIBLE INDIVIDUAL Diane P. Mann			22b TELEPHONE (Include Area Code) (217) 373-7223		22c OFFICE SYMBOL CECER-IMO

UNCLASSIFIED

6a. NAME OF PERFORMING ORGANIZATIONS (Cont'd):

US Army Construction Engineering Research Laboratory
University of Illinois
US Army Cold Regions Research and Engineering Laboratory

6c. ADDRESS (Cont'd):

PO Box 4005, Champaign, IL 61824-4005
Urbana, IL 61820
Hanover, NH 03755

UNCLASSIFIED

FOREWORD

This article is reprinted with permission from the Proceedings of the 9th Conference on Roofing Technology, "Putting Roofing Technology to Work," May 4-5, 1989, Gaithersburg, Maryland.

David M. Bailey is a principal investigator at the U.S. Army Construction Engineering Research Laboratory, Champaign, IL; Donald E. Brotherson is the Director of the Small Homes Council at the University of Illinois, Urbana-Champaign; and Wayne Tobiasson is a principal investigator at the U.S. Army Cold Regions Research and Engineering Laboratory, Hanover, New Hampshire.

The work was funded by the Headquarters, U.S. Army Corps of Engineers under project 4A162731AT41, "Military Facilities Engineering Technology"; Task C, "Operations/Management/Repair," Work Unit 044, "Roofing Maintenance Management System."

Accession For	
NTIS GRA&I	<input checked="checked" type="checkbox"/>
DTIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By	
Distribution/	
Availability Codes	
Dist	Avail and/or Special
A-1	

ROOFER: A MANAGEMENT TOOL FOR MAINTAINING BUILT-UP ROOFS

DAVID M. BAILEY
U.S. Army Construction
Engineering Research
Laboratory*
Champaign, Ill.

DONALD E. BROTHERSON
University of Illinois
Urbana, Ill.

WAYNE TOBIASSON
U.S. Army Cold Regions
Research and Engineering
Laboratory
Hanover, N.H.

The U.S. armed services have a very large inventory of buildings with bituminous built-up roof membranes. Millions of dollars are being spent annually to repair or replace these roofs. In the past this has been done using inconsistent management schemes. There was a need for a systematic procedure to evaluate these roofs, to determine priorities and to select repair strategies that would insure the maximum return on investment.

To respond to this need, the U.S. Army Construction Engineering Research Laboratory (USACERL), with the assistance of the U.S. Army Cold Regions Research and Engineering Laboratory (CRREL) and the U.S. Army Engineering and Housing Support Center (USAEHSC), is developing ROOFER, a roofing maintenance management system for built-up roofs. This work has been a team effort involving roofing experts from industry as well as from other branches of the military in an "on the roof" dynamic process involving more than 50 buildings at seven locations.¹ ROOFER provides building managers with a practical decision-making procedure that will identify problem roofs and select maintenance and repair strategies for roofs with bituminous membranes.

ROOFER comprises procedures for dividing the building roof into manageable sections, collecting and managing inventory information, inspection and condition evaluation, network management and project management. It utilizes many of the highly successful concepts developed by USACERL for the PAVER pavement maintenance management system.^{2,3}

NETWORK vs. PROJECT

Network management is defined as the process of making decisions regarding the management of a group of roof sections, such as all roof sections on a military installation or all roof sections on a specific building type such as barracks. Project management is the process of making decisions regarding the maintenance and repair of individual roof sections. When there are just a few roofs to manage, they can be kept track of on a project basis. When there are hundreds or thousands of roofs to manage, initial decisions should not be made on a project by project basis but on a network basis. ROOFER provides the tool for network decisions as well as the information needed to initiate projects. Network-level management includes managing all of the roofs on an installation, in a geographic area or even service-wide. Management decisions are made in a general way and do not require

the same amount of information that a project-level decision requires. What is needed is a way of comparing the condition of all of the roofs in the network using a consistent evaluation technique. Network-level information is used to develop a rational means of repairing or replacing problem roofs within the network to meet specific performance levels. Short- and long-term plans can be developed that will respond to actual or anticipated needs rather than employing crisis management or spending money on roofs in less need than others.

DIVIDING A ROOF INTO SECTIONS

Building roofs are divided into identifiable sections in order to increase management efficiency. Managing roofs at the section level provides a better means of evaluating condition and determining maintenance and repair needs. For example: A roof section that is in poor condition will not detract from the condition of a roof section in good condition on the same building, and conditions indicating replacement of one section would not necessarily indicate replacement of the entire building roof.

Roof sections are generally delineated by firewalls, expansion joints or area dividers. Areas having different roofing systems, different amounts of roof traffic and/or rooftop equipment or significantly different occupancies below the roof are designated into separate sections.

INVENTORY AND DATA MANAGEMENT

The roof inventory is the foundation of ROOFER. It provides the information needed by engineering personnel to select repair techniques and to determine the suitability of replacement systems. A well maintained inventory will provide a history of each roof section and a record of roof performance that can be used to determine which built up roof systems are the most suitable for use on a particular building type or occupancy.

For each building, general information concerning building name, number, location and occupancy are collected. A building roof plan is developed that shows overall dimensions and identifies each roof section. This information, along with contract drawings, specifications, submittals and as-built drawings, is also collected and stored in a building folder.

For each roof section, data are collected on the type of structural frame, deck, vapor retarder, insulation, membrane and flashing. Worksheets with checklists are used to ensure uniformity in reporting. A roof section plan is drawn to scale on the roof inspection worksheet, showing all physical features, including perimeter conditions, rooftop equipment

**The views of the authors do not purport to reflect the position of the Department of the Army or the Department of Defense.*

and projections, drains, scuppers, walkways, etc. This information is then stored in a section folder.

Collecting the inventory data can be a frustrating experience. The inventory information is obtained from a variety of sources such as as-built drawings, specifications and an inspection of the roof itself. The core cuts that are made to determine the moisture content of the insulation should also be used to verify the components of the roofing system. However tedious, the effort is needed and important since it establishes the foundation of the ROOFER system.

INSPECTION AND CONDITION EVALUATION

Condition Rating

The condition rating is the key component of any maintenance management system. The ROOFER system uses three separate condition indexes:

- MCI—the membrane condition index
- FCI—the flashing condition index
- ICI—the insulation condition index

Each of these indexes provides a measure of that component's ability to perform its function, the needed level of repair, and the potential for leaks. Numerical indexes range from 0 to 100, with 100 representing excellent condition. Treating each component separately provides a more accurate assessment of component condition and needed maintenance and repair. The MCI and FCI are determined by visual inspection, and the ICI is determined by evaluation techniques such as infrared, electrical capacitance or nuclear.

Visual Inspection

The MCI and FCI indexes for a roof section are based on the quantity, severity and type of distresses present on the roof section.

The visual inspection technique, a distress manual and computation procedures are described in detail in USA-CERL Technical Report M-87/13, "Membrane and Flashing Condition Indexes for Built-Up Roofs, Volume II: Inspection and Distress Manual."

Five steps are followed in the procedure:

1. **Determine type, severity and quantity of distress.** The type, severity and particular defect for each distress is defined in the "Inspection and Distress Manual." Six flashing distresses and 10 membrane distresses are identified (Table 1), and low, medium and high severity levels of distress are described. For a typical distress such as blisters, low, medium and high levels are described (Figure 1), and eight color photographs are used to illustrate the descriptions. The method of measuring the distress density is also defined. Color photographs are used throughout the manual to illustrate the other 15 distresses.
2. **Determine deduct values for each distress.** Deduct values for each distress and severity level are determined from a series of charts similar to Figure 2.
3. **Determine corrected total deduct value.** The deduct values are entered on the roof section rating form, and a corrected deduct value is determined using a correction chart that takes into account the effect of multiple distresses (Figure 3).
4. **Determine component condition index.** The condition index is calculated by subtracting the corrected deduct value from 100.

5. **Determine component condition rating.** The condition rating is determined from Table 2.

NON-DESTRUCTIVE MOISTURE EVALUATION

A complete evaluation of an insulated roofing system requires that the insulation be inspected to determine if excessive moisture is present. Moisture reduces the thermal value of the insulation and may also reduce the bond between it and the membrane or deck. Water in insulation adds to the weight the structural system must support and may cause corrosion of fasteners and deterioration of the roofing system.

By using non-destructive moisture evaluation techniques such as infrared (IR), nuclear or capacitance, areas of probable wet insulation can be determined.⁵ Core samples must be taken to verify the probable wet areas and to determine the moisture content of the insulation. Knowing the type and amount of wet insulation and its moisture content, the insulation condition index (ICI) for a section can be calculated.

ROOF CONDITION INDEX

The membrane, flashing and insulation condition indexes are combined to determine the roof condition index (RCI). This provides a useful method of evaluating the overall condition of a roof section and a method of comparing conditions between roof sections. The RCI allows the user to rank individual roof sections according to their ability to perform.

The three component indexes (MCI, FCI and ICI) have a direct relationship to determining the needs for maintenance and repair (M&R) of a roof section. Similarly, the RCI provides an overall indication of M&R needs.

Like the component indexes, the RCI is based on the same scale of 0 to 100, with 100 indicating that only routine maintenance is needed. It is calculated by giving the greatest weight to the component with the lowest condition index and a lesser weight to the remaining indexes. For a roof section with insulation, the lowest of the three indexes has 70 percent of the weighting and the other two indexes each have 15 percent of the weighting. Table 3 lists the qualitative condition ratings associated with the RCI.

NETWORK MANAGEMENT

Network management uses the collected information to develop long-range budget projections and work requirements for the network.

The ROOFER program can generate a series of reports for making network management decisions. These reports include:

Section Inventory List

The section inventory list report (Figure 4) provides a list of the surveyed roof sections. For each section, the type of membrane insulation, and deck as well as roof slope and area are provided.

Inspection Scheduling

The inspection schedule report is used to prepare a plan for scheduling future ROOFER inspections for roof sections based on the RCI. The report produces a plot and list of the roof sections to be inspected during the next three years for all of the roof sections of a particular building use, membrane type or section area.

Condition Frequency

The condition frequency report informs management of the current condition of the roof network and helps plan for future maintenance and repair. The roof sections included in the report can be selected by building use, membrane, insulation and/or deck type, roof slope, section area or age. The report lists, by section and area, the number and percentages for the different RCI ranges and provides a graphical plot of the frequency of occurrences. Figure 5 is a typical report for a group of buildings at a military installation.

Using the different selection options, the effects of conditions such as deck type, insulation type or slope on overall condition can be examined.

Roof Condition Index

The roof condition index report (Figure 6) lists roof sections and component indexes in order of increasing RCI. The report can be sorted based on building use, membrane, insulation, deck type, roof slope, section area or age to provide management with the background information needed to select and prioritize roof sections for maintenance and repair. The RCI, building use and age, as well as available budget, provide the criteria for project selection.

Project Management

Project management uses the three component condition indexes and distress data that were determined for a section to provide valuable information regarding the condition of the roof section and required maintenance and repair. This information when combined with life-cycle predictions can be used to identify M&R alternatives.

Field Tests

Field tests of the ROOFER program were performed at Ft. Meade last year, and preliminary findings indicate that the system works well. The forms used for data collection and the microcomputer program for analyzing the data provided the planning for long-range repair and replacement of the built-up roof network at Ft. Meade. They did not present any problems to the contractor performing the work.

CONCLUSIONS

This paper has described a comprehensive management system for built up roof systems. The procedures presented are being programmed for microcomputer use as part of the ROOFER program. Inventory, inspection, condition evaluation and network management techniques have been developed, and the system has been designed to enable the incorporation of other low-slope roofing systems in the future. ROOFER will be available to private industry through a nongovernment distribution agency.

REFERENCES

- ¹ Shahin, M.Y., Bailey, D.M., Brotherson, D.E. and "Membrane and Flashing Condition Indexes for Built-Up Roofs, Volume I: Development of the Procedure," Technical Report M-87/13, U.S. Army Construction Engineering Research Laboratory (USA-CERL), September 1987.
- ² Shahin, M.Y. and Kohn, S.D., "Pavement Maintenance Management for Roads and Parking Lots," Technical Report M-294, U.S. Army Construction Engineering Research Laboratory (USA-CERL), October 1981.
- ³ Shahin, M.Y., Cation, K.A. and Broten, M.R., "Micro PAVER Concept and Development, Airport Pavement Management System," Report No. DOT/FAA/PM-87/7, Federal Aviation Administration (FAA), July 1987.
- ⁴ Shahin, M.Y., Bailey, D.M. and Brotherson, D.E., "Membrane and Flashing Condition Indexes for Built-Up Roofs, Volume II: Inspection and Distress Manual," Technical Report M-87/13, U.S. Army Construction Engineering Research Laboratory (USA-CERL), September 1987.
- ⁵ Tobiasson, W. and Korhonen, C., "Roof Moisture Surveys: Yesterday, Today and Tomorrow," CRREL Miscellaneous Paper 2040, September 1985.

ACKNOWLEDGMENTS

The authors wish to acknowledge the contributions of Dr. Mohamed Shahin, USA-CERL, Champaign, IL; Mr. John Bradford, Bradford Roofing and Insulation Co., Billings, MT; and Mr. Dwight Jennings, INSPEC, Minneapolis, MN, who were key members of the development team. They participated in field testing and validation efforts. The following team members are also recognized for their contributions and assistance: Mr. Robert Alumbaugh, Navy Civil Engineering Laboratory (NCEL); Mr. Mark de Ogburn, Southern Division Naval Facilities Engineering Command (SOUTHNAVFACENGCOM); Mr. Dennis Firman, Air Force Engineering and Services Center (AFESC); Mr. Ed Humm, NCEL; Mr. Al Knehans, USAEHSC; Mr. Myer Rosenfield, USA-CERL; and Mr. Tom Wallace, Northern Division Naval Facilities Engineering Command (NORTHNAVFACENGCOM).

Flashing	Membrane
Base Flashing	Blisters
Metal Cap Flashing	Ridges
Embedded Edge Metal	Splits
Flashed Penetrations	Holes
Pitch Pans	Surface Deterioration
Drains and Scuppers	Slippage
	Patching
	Debris and Vegetation
	Equipment Supports
	Ponding

Table 1 Built-up roofing distresses

Condition Index	Rating
86 - 100	Excellent
71 - 85	Very Good
56 - 70	Good
41 - 55	Fair
26 - 40	Poor
11 - 25	Very Poor
0 - 10	Failed

Table 2 Condition ratings


RCI	Roof Condition Rating
86 - 100	Routine Maintenance
71 - 85	Minor Repairs Needed
56 - 70	Moderate Repairs Needed
41 - 55	Major Repairs Needed
26 - 40	Replacement Probable
11 - 25	Replacement Needed
0 - 10	Replacement Critical

Table 3 Maintenance and repair recommendations

BLISTERS

Description: Blisters are round or elongated raised areas of the membrane that are filled with air.

Note: Blisters and ridges are difficult to differentiate at the low and medium severity levels. The rating error will be insignificant because of the similarity in the deduct curves. At high severity, however, it is important to distinguish between the two distresses due to their different leak potentials.



Graphic Representation of Blister

Severity Levels:

Low:

1. The raised areas are noticeable by vision or feel. The surfacing is still in place and the felts are not exposed.

Medium:

1. The felts are exposed or show deterioration.

High:

1. The blisters are broken.

Measurement:

1. Measure the length and width of the blister in lineal feet and calculate the area (length times width). If the distance between individual blisters is less than 5 feet, measure the entire affected area in square feet.
2. When large quantities of this problem are present (especially on large roofs), the representative sampling technique can be used.

Density:

$$\frac{A}{B} \times 100 = \text{Problem Density}$$

where A = total area of membrane blisters (sq ft)

B = total area of roof section being rated (sq ft)

Note: The problem density is calculated for each existing severity level.

Figure 1 Distress description and severity levels for blisters




Figure 2 Deduct value curve for blisters




Figure 3 Corrected deduct values for membranes

DATE	SEP/21/1988	SECTION INVENTORY REPORT			PAGE	1
INSTALLATION	00000	FT XXXXX				
BLDG NUMBER/NAME	SEC	MEMBRANE	INSULATION	DECK	SLOPE	AREA
FACILITY CLASS	ID	TYPE	TYPE	TYPE		(SqFt)
393 CAREFR CENTER HOUSING & COMM	A	BUR Asphalt	GLASS FIBER	STEEL	1/2	10368
4407 TELEPHONE EXCHANGE OPER & TRAIN	A	BUR Asphalt	WOOD FIBERBD	GYPSPUM Gypsum Form	1/8	7028
	B	BUR Asphalt	PERLITE	CONCRETE STD Cast-In-Pi	1/8	258
6600 OFFICERS CLUB HOUSING & COMM	A	BUR Asphalt	PERLITE POLYURETHANE	STEEL	1/4	22800
	B	BUR Bit Unk	UNKNOWN	STEEL	1/8	2003
8478 ENLISTED MEN'S BARRACKS HOUSING & COMM	A	BUR Asphalt	FILL-Lt Conc	CONCRETE STD Cast-In-Pi	1/8	10374
	B	BUR Asphalt	FILL-Lt Conc	CONCRETE STD Cast-In-Pi	1/4	5195
8501 REGIMENTAL HEADQUARTERS OPER & TRAIN	A	BUR Bit Unk	WOOD FIBERBD	CONCRETE STD Cast-In-Pi	1/2	3100
TOTALS		Sections	8	Area	51126	

Figure 4 Section inventory report

DATE	SEP/21/1988	RCI FREQUENCY PLOT	PAGE	1
INSTALLATION	00000	FT XXXXX		
SLECTION CRITERIA				
Condition Index	-- RCI	ALL		
Building Number		ALL		
Facility Class		ALL		
Membrane Type		ALL		
Insulation Type		ALL		
Deck Type		ALL		
Roof Slope		ALL		
Section Area		ALL		
Last Construction Year		ALL		
Last Inspection Year		ALL		
PLOT OF RCI FREQUENCY REPO:				
NO	S&C	N	CONDITION	
0	0	0	FAILED	
3	3	5	VERY POOR	*****
1	2	2	POOR	***
8	15	15	FAIR	*****
15	27	27	GOOD	*****
26	47	47	VERY GOOD	*****
2	4	4	EXCELLENT	****
55				
				NO. OF SECTIONS
TOTAL NUMBER OF SECTIONS				55
AVERAGE RCI				66
NUMBER OF MISSING VALUES				0

Figure 5 RCI frequency plot

DATE	SEP/21/1988	RCI REPORT	PAGE	1
INSTALLATION	00000	FT XXXXX		
BLDG NUMBER/NAME	SECTION ID/SLOPE/MEMBRANE	SECT AREA	LAST INSP	RCI/ICI
FACILITY CLASS	INSULATION TYPE(S)	(SqFt)	YEAR	RCI
8501 REGIMENTAL HEADQUARTERS OPER & TRAIN	A 1/2 BUR Bit Unk WOOD FIBERBD CONCRETE STD Cast-In-Pi	3100	1961/1986	82/ 60/ 27 41
4407 TELEPHONE EXCHANGE OPER & TRAIN	A 1/8 BUR Asphalt WOOD FIBERBD GYPSPUM Gypsum Form	7028	1955/1987	96/ 20/ 80 42
8478 ENLISTED MEN'S BARRACKS HOUSING & COMM	B 1/8 BUR Asphalt FILL-Lt Conc CONCRETE STD Cast-In-Pi	5195	1955/1987	78/ 58/100 68
393 CAREFR CENTER HOUSING & COMM	A 1/2 BUR Asphalt GLASS FIBER STEEL	10368	1984/1987	78/ 63/100 71
6600 OFFICERS CLUB HOUSING & COMM	B 1/8 BUR Bit Unk UNKNOWN STEEL	2003	1982/1987	70/ 80/--- 74
4407 TELEPHONE EXCHANGE OPER & TRAIN	B 1/8 BUR Asphalt PERLITE CONCRETE STD Cast-In-Pi	258	1955/1987	94/ 68/100 77
8478 ENLISTED MEN'S BARRACKS HOUSING & COMM	A 1/8 BUR Asphalt FILL-Lt Conc CONCRETE STD Cast-In-Pi	10374	1955/1987	87/ 70/100 77
6600 OFFICERS CLUB HOUSING & COMM	A 1/4 BUR Asphalt PERLITE POLYURETHANE STEEL	22800	1982/1987	96/ 76/100 83

Figure 6 RCI report

USACERL DISTRIBUTION

Chief of Engineers
ATTN: CEIM-SL (2)
ATTN: CECW-P
ATTN: CECW
ATTN: CECW-O
ATTN: CECW-P
ATTN: CECW-RR
ATTN: CEEC
ATTN: CEEC-C
ATTN: CEEC-E
ATTN: CERD
ATTN: CERD-C
ATTN: CERD-M
ATTN: CERM
ATTN: DAEN-ZCE
ATTN: DAEN-ZCI
ATTN: DAEN-ZCM
ATTN: DAEN-ZCZ

CEHSC ATTN: CEHSC-ZC 22060
ATTN: DET III 79906
ATTN: CEHSC-F 22060
ATTN: CEHSC-TE 22060
ATTN: Canadian Liaison Officer 65473
ATTN: German Liaison Staff 65473
ATTN: French Liaison Officer 65473
ATTN: Water Resources Center 22060

US Army Engineer Districts
ATTN: Library (43)

US Army Engr Divisions
ATTN: Library (14)

US Army Europe
ODCS Engineer 09403
ATTN: AEAEN-FE
ATTN: AEAEN

V Corps
ATTN: DEH (11)

VII Corps
ATTN: DEH (16)

21st Support Command
ATTN: DEH (12)

USA Berlin
ATTN: DEH (9)

Allied Command Europe (ACE)
ATTN: ACSGB 09011
ATTN: SHHB Engineer 09055
ATTN: AEUS 09081

USAF
ATTN: AESE EN-D 09019

8th USA Korea (19)

ROK/US Combined Forces Cmd 96301
ATTN: EUSA-HHC-CFC/Engr

USA Japan (USARJ)
ATTN: DCSEN 96343
ATTN: Facilities Engineer 96343
ATTN: DEH Okinawa 96331

Area Engineer, AEDC-Area Office
Arnold Air Force Station, TN 37389

416th Engineer Command 60623
ATTN: Facilities Engineer

US Military Academy 10966
ATTN: Facilities Engineer
ATTN: Dept of Geography & Computer Science
ATTN: MAEN-A

AMC - Dir., Inst., & Svcs
ATTN: DEH (23)

DLA ATTN: DLA WI 22304

DNA ATTN: NADS 20305

FORSCOM
FORSCOM Engineer, ATTN: Spt Det.
ATTN: Facilities Engineer (27)

HSC
Ft. Sam Houston AMC 78234
ATTN: HSL-O-F
Fitzsimons AMC 80045
ATTN: HSHG-DEH
Walter Reed AMC 20307
ATTN: Facilities Engineer

INSCOM - Ch, Instl. Div.
Arlington Hall Station (4) 22212
ATTN: Facilities Engineer
Vint Hill Farms Station 22186
ATTN: IAV-DEH

USA AMCCOM 61279
ATTN: AMSMC-RI
ATTN: AMSMC-IS

Military Dist of Washington
ATTN: DEH
Cameron Station (3) 22314
Fort Lesley J. McNair 20319
Fort Myer 22211

Military Traffic Mgmt Command
Falls Church 20315
Oakland Army Base 94626
Bayonne 07002
Sunny Point MOT 28461

NARADCOM, ATTN: DRDNA-F 01760

TARCOM, Fac, Div. 48090

TRADOC
HQ, TRADOC, ATTN: ATEN-DEH 23651
ATTN: DEH (18)

TSARCOM, ATTN: STSAS-F 63120

USAIS
Fort Huachuca 85613
ATTN: Facilities Engineer (3)
Fort Ritchie 21719

WESTCOM
Fort Shafter 96858
ATTN: DEH
ATTN: APEN-A

SHAPE 09055
ATTN: Survivability Sect. CCB-OPS
ATTN: Infrastructure Branch, LANDA

HQ USEUCOM 09128
ATTN: ECJ 47-LOE

Fort Belvoir, VA 22060
ATTN: British Liaison Officer
ATTN: Australian Liaison Officer
ATTN: Engr Studies Center
ATTN: Engr Topographic Lab
ATTN: ATZA TE-SW
ATTN: STRBE-BLURE

CECRL, ATTN: Library 03755

WES, ATTN: Library 3918

HQ, XVIII Airborne Corps and
Ft. Bragg 28307
ATTN: ATZA DEH-LE

Chanute AFB, IL 61868
3345 CES/DE, Stop 27

Norton AFB, CA 92409
ATTN: AIRCE-MX/DE

Tyndall AFB, FL 32403
AFESC/Engineering & Service Lab

NAVFAC
ATTN: Division Offices (11)
ATTN: Facilities Engr Cmd (9)
ATTN: Naval Public Works Ctr (9)
ATTN: Naval Civil Engr Lab (3)
ATTN: Naval Constr Battalion Ctr

Engineering Societies Library
New York, NY 10017

National Guard Bureau 20310
Installation Division

US Government Printing Office 22304
Receiving/Depository Section (2)

US Army Env. Hygiene Agency
ATTN: HSHB-ME 21010

Nat'l Institute of Standards & Tech 20899

Defense Technical Info. Center 22314
ATTN: DDA (2)

317
10/89